




Diaphragm shock assembly instructions

Step 1






- (A) Shock cartridge cap
- (B) Shock cap bushing
- (C) Spacer
- (D) Shock cartridge
- (E) Spring cup
- (F) Tool
- (G) Shock cap
- (H) Shock cartridge C-clip
- (I) Shock adjustment nut
- (J) Shock piston





1:1 scale oring standard grid



Step 2





Step 3





Step 4



Low pressure setup



High pressure setup



Step 5



Video manual
www.gmade.net

For any inquiry or detailed
assembly explanation,
Please visit our
Gmade website.

GMade®
www.gmade.net

Made in Korea